MOTOROLA
intelligence everywhere™

HT1250·LS+™ Portable Firmware / PassPort® Firmware Compatibility Matrix		HT1250·LS+ Portable Firmware Versions						
		R05.13.08	R05.09.11	R05.09.06	R05.09.03	R05.09.02	R05.08.07	R05.08.03
PassPort Firmware Versions	R08.02.05 or later	✓ A	✓	✗	✗	✗	✗	✗
	R08.00.18	✓	✓	✗	✗	✗	✗	✗
	R07.02.09	✓ B	✓ B	✓ B	✓	✓	✗	✗
	R06.02.16	✗ C	✗ C	✗ C	✗ D	✓	✓	✓

✓ = Compatible   ✗ = NOT Compatible

HT1250·LS⁺ Portable Firmware / PassPort Firmware Compatibility Matrix

Notes:

A   PassPort Firmware R08.02.05 or higher adds support for 700Mhz Band Change to 757Mhz; for 700Mhz Rebanded PassPort operation, HT1250·LS⁺ Portable Firmware R05.13.08 or higher is REQUIRED.

B   PassPort Firmware R07.02.09 or higher adds support for VHF; for VHF PassPort operation, HT1250·LS⁺ Portable Firmware R05.09.03 or higher is REQUIRED.

C   Compatibility between PassPort Firmware R07.01.13 and lower and HT1250·LS⁺ Portable Firmware R05.09.03 or higher is not verified.

D   Compatibility between PassPort Firmware R06.02.16 and HT1250·LS⁺ Portable Firmware R05.09.02 is not verified.

CDM1550·LS+™ Mobile Firmware / PassPort® Firmware Compatibility Matrix		CDM1550·LS+ Mobile Firmware Versions						
		R05.07.01	R05.05.15	R05.05.12	R05.05.10	R05.05.04	R05.05.02	R05.04.01
PassPort Firmware Versions	R08.02.05 or later	✓ A	✓	✓	✓	✗	✗	✗
	R07.02.09	✓	✓	✓	✓	✗	✗	✗
	R07.01.13	✓	✓	✓	✓	✓	✓	✓
	R06.02.16	✗	✗ B	✗ C	✓	✓	✓	✓

✓ = Compatible   ✗ = NOT Compatible

![MOTOROLA intelligence everywhere™]

CDM1550·LS⁺ Mobile Firmware / PassPort Firmware Compatibility Matrix

Notes:

A   PassPort Firmware R08.02.05 or higher adds support for 700Mhz Band Change to 757Mhz; for 700Mhz Rebanded PassPort operation, HT1250·LS⁺ Mobile Firmware R05.07.01 or higher is REQUIRED.

B   Compatibility between PassPort Firmware R06.02.16 and CDM1550·LS⁺ Mobile Firmware R05.05.12 is not verified.

C   Compatibility between PassPort Firmware R06.02.16 and CDM1550·LS⁺ Mobile Firmware R05.05.10 is not verified.

PassPort® CPS (PPCPS) / PassPort Firmware Compatibility Matrix		PassPort CPS (PPCPS) Versions			
		R05.02.03 or later	R05.00.10	R04.03.24	R04.00.01 B
PassPort Firmware Versions	R08.02.05 or later	✓ A	✓	✗	✗
	R07.02.09	✓	✓	✓	✗
	R07.01.13	✗	✗	✗	✓
	R06.02.16	✗	✗	✗	✗

✓ = Compatible   ✗ = NOT Compatible

PassPort CPS (PPCPS) / PassPort Firmware Compatibility Matrix

Notes:

A   PassPort Firmware R08.02.05 or higher adds support for 700Mhz Band Change to 757Mhz; for 700Mhz Rebanded PassPort operation, PassPort CPS (PPCPS) R05.02.03 or higher is REQUIRED.   For Emergency Declaration via Rear Accessory Input, R05.02.03 must be used to configured the R08.02.05 Passport Radio.

.

B   PassPort CPS (PPCPS) R04.00.01 is compatible with PassPort Firmware R07.01.11, R07.01.12, and R07.01.13.

この行は存在しません

PassPort® CPS (PPCPS) / Professional Series CPS Compatibility Matrix		PassPort CPS (PPCPS) Versions			
		R05.02.03 or later	R05.00.10	R04.03.24	R04.00.01
Professional Series CPS Versions	R06.10.01 or higher	✓ A	✓	✓	✗ C
	R06.05.03	✓	✓	✓	✗ C
	R06.05.00	✓	✓	✓	✓
	R06.04.00	✗	✗ B	✓	✓
	R06.03.00	✗	✗ B	✗	✓

✓ = Compatible   ✗ = NOT Compatible

PassPort CPS (PPCPS) / Professional Series CPS Compatibility Matrix

Notes:

A   **Professional Series CPS R06.10.01 or higher adds support for 700Mhz Band Change to 757Mhz; for 700Mhz Rebanded PassPort operation, PassPort CPS (PPCPS) R05.02.03 or higher is REQUIRED.**

B   **Compatibility between PassPort CPS (PPCPS) R04.03.24 and Professional Series CPS R06.04.00 or earlier is not verified.**

C   **Compatibility between PassPort CPS (PPCPS) R03.02.00 and Professional Series CPS R06.05.03 is not verified.**