Professional Series CPS R06.11.05
Customer Release Notes

This release of the CPS application supports all models/bands of the Professional Series Portable and Mobile Radios. For any questions, please contact Customer Resources at 1-800-927-2744.

I.   Enhancements

Item #1: Codeplug Recovery

The CPS now has the capability of recovering some cases of "EEPROM CS ERROR" failure mode. The location of the corruption must be in the CPS modifiable area of the codeplug for the failure mode to be corrected. The radio will be programmed with a factory default codeplug during the recovery. If the corruption location is not in the CPS modifiable area, the radio will not be recovered by CPS.

II.   Corrections

Item #1: Microsoft Vista Compatibility Issue

This release corrects a Microsoft Vista Compatibility issue that caused the CPS to crash.

Item #2: Programming in Test Mode

The CPS will now place the radio in test mode before programming is started.

Item #3: Error Message Change

Error messages changed for user clarity.

III.   Known issues

None