

Professional Series Portable Firmware R05.13.09 Customer Release Notes

NOTE: Professional CPS R06.09.06 or later must be used with this firmware.

This release of radio firmware <u>only supports the Prime</u> family of Professional Series Portable Radios. All bands in this family are supported. For any questions, please contact Customer Resources at 1-800-927-2744.

I. Enhancements

None

II. Corrections

Item #1: Intermittent low audio in LTR

While operating on an LTR system in narrowband mode an older LVZIF design radio may exhibit low audio during a second reception while within the scan hang timer window.

III. Known issues

Item #1: Call Light not working with Option Board

The Call Light does not work when Option Board Type is set to Simple Option Interface/Advanced Option Interface.

May 2, 2008