

Professional Series Mobile Firmware Upgrade Kit R05.10.03 Customer Release Notes

NOTE: Professional CPS R06.12.09 and later is recommended with this firmware.

This release of radio firmware ALL families of Professional Series Mobile Radios. For any questions, please contact Customer Resources at 1-800-927-2744.

I. <u>Enhancements</u>

None

II. <u>Corrections</u>

CDM1550 may not display alias when receiving MDC-1200 with Firmware R05.10.01 or later.

III. Known Issues

None

MOTOROLA SOLUTIONS and the Stylized M Logo are registered in the U.S. Patent & Trademark Office.

All other product or service names are the property of their respective owners.

© Motorola Solutions, Inc. 2013.

July 10th, 2013 Page 1 of 1