

Professional Series Portable Firmware UpgradeKit R05.14.03 Customer Release Notes

NOTE: Professional CPS R06.11.05 or later is recommended to be used with this firmware.

This release of radio firmware <u>only supports the Prime</u> family of Professional Series Portable Radios. All bands in this family are supported. For any questions, please contact Customer Resources at 1-800-927-2744.

I. <u>Enhancements</u>

None

II. <u>Corrections</u>

Item #1: MDC1200 Message not displayed

When Option Board Type is configured to use Simple/Advanced/Advanced & Voice Storage Option interface the radio will not display an incoming MDC1200 Message.

III. Known issues

None

June 15, 2009

MOTOROLA and the Stylized M Logo are registered in the U.S. Patent & Trademark Office. All other product or service names are the property of their respective owners. © Motorola, Inc. 2009.